## KNOW ALL MEN BY THESE PRESENTS, TO WIT:

THAT HERITAGE BUILDERS LTD. OF ROANOKE IS THE FEE SIMPLE OWNER AND PROPRIETOR OF THE LAND SHOWN HEREON TO BE SUBDIVIDED, BOUNDED BY OUTSIDE CORNERS 1 THROUGH 15 TO 1, INCLUSIVE, WHICH COMPRISES ALL OF THE LAND CONVEYED TO SAID OWNER BY G. L. MATTERN & RUBY M. MATTERN BY DEED DATED 27 "JANUARY 1999, AND RECORDED IN THE CLERK'S OFFICE OF THE CIRCUIT COURT OF THE CITY OF SALEM IN DEED BOOK \_\_\_\_\_, AT PAGE \_\_\_\_\_

THE SAID OWNER HEREBY DEDICATES TO THE CITY OF SALEM EASEMENTS FOR PUBLIC UTILITIES, SANITARY SEWER, WATER, AND DRAINAGE PURPOSES AS SHOWN AND NOTED HEREON AND SAID OWNER FURTHER CERTIFIES THAT IT HAS SUBDIVIDED THE LAND AS SHOWN HEREON ENTIRELY OF ITS OWN FREE WILL AND CONSENT AND PURSUANT TO AND IN COMPLIANCE WITH SECTION 15.1-465 THROUGH 15.1-485 OF VIRGINIA CODE OF 1950 AS AMENDED TO DATE AND FURTHER PURSUANT TO AND IN COMPLIANCE WITH CHAPTER 26 "SUBDIVISIONS" AS AMENDED TO DATE OF THE GENERAL ORDINANCE OF THE CITY OF SALEM, VIRGINIA, AND SECTION BA OF THE CITY OF SALEM SOIL EROSION & SEDIMENT ORDINANCE.

MINESS THE FOLLOWING SIGNATURES AND SEALS ON THIS 10 TH DAY OF DECEMBER. 1998.

HERITAGE BUILDERS LTD. OF POANOKE, OWNER

STATE OF VIRGINIA

COUNTY OF ROANDKE

I, ARLENE M. THOMAS ..... A NOTARY PUBLIC IN AND FOR THE AFORESAID COUNTY AND STATE DO HEREBY CERTIFY THAT LEWIS C. JAMISON, PRESIDENT OF HERITAGE BUILDERS LTD., OWNER, WHOSE NAME IS SIGNED TO THE FOREGOING WRITING DATED 10 DECEYMBER. 1998, HAS PERSONALLY APPEARED BEFORE ME IN MY AFORESAID COLINTY AND STATE AND ACKNOWLEDGED THE SAME ON DECEMBER 10 1998.

MY COMMISSION EXPIRES \_\_MARCH 31 2000

	CURVE TABLE					
CURVE	RADIUS	LENGTH	TANGENT	CHORD	BEARING	DELTA
C1	135.00'	116.80'	62.34'	113.19'	N 73"25"02" E	49'34'17"
C2	135.00'	85.14'	44.04'	83.73'	N 8008'11" E	36 77'59"
C3	135.00'	31.66'	15.90'	31.59'	N 55"21"02" E	13'26'18"
C4	365.00'	195.66'	100.78'	194.29'	N 6404'00" E	305213"
C5	365.00'	85.56'	42.98'	85.36'	N 5520'48" E	13'25'50"
C6	365.00'	75.44'	37.86'	75.31'	N 6758'59" E	11'50'32"
C7	365.00'	35.66'	17.84'	35.64'	N 76"42"11" E	05'35'51"
<i>C8</i>	285.00'	108.07'	54.69'	107.43'	N 68'38'18" E	21'43'36"
<i>C9</i>	285.00'	65.18'	32.73'	65.04'	N 72"57"01" E	1306'12"
C10	285.00'	42.89'	21.49'	42.85'	N 6205'12" E	08'37'24"
C11	290.00'	111.75'	<i>56.58</i> ′	111.06'	N 68'48'51" E	2204'42'
C12	290.00'	42.45'	21.26'	42.41'	N 61"58"07" E	0823'12"
C13	290.00'	69.30'	34.82'	<i>69.13</i> ′	N 7300'28" E	13'41'30"
C14	25.00'	21.90'	11.71'	21.20'	N 54"45"39" E	5071'07"
C15	25.00'	16.19'	8.39	15.90'	N 6178'21" E	3705'43'
C16	25.00°	5.71'	2.87'	5.70'	N 3672'48" E	1305'24"
C17	45.00'	233.60'	31.63'	52.13'	S 04'50'50" E	290'58'08
C18	46.00'	60.91'	<i>35.86</i> ′	56.56	N 6736'13" E	75'52'14"
C19	45.00'	50.62'	28.22'	48.10'	5 42'56'12" E	6302'56'
C20	46.00'	48.33'	26.66'	46.14'	S 18'41'15" W	6071'58"
C21	45.00'	73.74'	47.51'	<i>66.10</i> ′	N 8577'16" W	91"51'00"
C22	25.00'	27.31'	15.20'	25.97'	N 70'39'39" W	62'35'45'
C23	25.00°	26.08'	14.37'	24.91'	N 6974'43" W	59'45'55'
C24	25.00'	1.24'	0.62'	1.23'	5 79"27"24" W	02'49'50'
C25	260.00'	91.97'	46.47'	91.49'	5 6754'30" W	2075'59"
C26	260.00'	80.24'	40.44'	79.92'	5 6972'01" W	17'40'55"
C27	260.00'	11.73'	5.86'	11.73'	S 59"04"02" W	02'35'04"
C28	315.00'	119.45'	60.45	118.73	S 68'38'18" W	21'43'36"
C29	315.00'	69.54	34.91'	69.40°	S 64°05'58" W	12'38'56"
C30	315.00'	49.91'	25.01'	49.86'	S 7457'47" W	0904'40'
C31	335.00'	180.49'	92.50'	178.32'	5 6404'00" W	305213"
C32	<i>335.00</i> ′	35.25'	17.64	35.23'	S 7629'15" W	0671'43"
C33	<i>335.00</i> ′	81.20'	40.80'	81.00'	S 66'31'45" W	135317"
C34	335.00'	54.04'	32.12'	63.95	S 54'06'30" W	10'57'13"
C35	165.00'	147.14'	78.87	142.31'	S 7470'43" W	5175'39"
C36	165.00'	22.06'	11.05'	22.04'	S 52"27"42" W	0739'37'
C37	165.00'	77.33'	39.39'	76.63'	S 69'43'07" W	26'51'12"
C38	165.00'	47.75'	24.04'	47.58'	N 88'33'53" W	16'34'50"
C39	48.00'	30.79'	15.94'	30.26'	N 16'32'03" E	36'44'53'

NOTES:

1. THIS PLAT IS BASED ON A CURRENT FIELD SURVEY.

3. IRON PINS AT ALL CORNERS UNLESS OTHERWISE NOTED.

PROPERTY NOT SHOWN HEREON.

2. THIS PLAT WAS PREPARED WITHOUT THE BENEFIT OF A CURRENT

TITLE REPORT AND THERE MAY EXIST ENCUMBRANCES WHICH AFFECT THE


4. A PORTION OF THIS PROPERTY DOES LIE WITHIN THE LIMITS OF A 100 YEAR FLOOD BOUNDARY AS DESIGNATED BY FEMA. THIS OPINION IS BASED ON

VERIFIED BY ACTUAL FIELD ELEVATIONS. SEE COMMUNITY PANEL

\$510141 0043 D, MAP \$51161C0043 D DATED OCTOBER 15, 1993.

AN INSPECTION OF THE FLOOD INSURANCE RATE MAPS AND HAS NOT BEEN

BOUN	DARY COOF	RDINATES				
ORIGIN	OF COORDINATE	TS ASSUMES				
CORNER	NORTHING	EASTING				
1	6490.16468	4463.16751				
2	6504.50852	4545.66244				
3	6646.06353	4488.91534				
4	<i>6665.67900</i>	4536.40642				
. 5	6794.52524	4808.26234				
6	7061.22200	4733.20700				
7	6947.95499	5245.52980				
8	<i>6527.59203</i>	5185.62844				
9	6512.36983	5071.64035				
10	6509.40291	4993.02818				
11	<i>6530.37600</i>	4994.07400				
12	<i>6361.60535</i>	4614.34586				
13	<i>6359.76835</i>	4514.16728				
14	6459.96300	4502.12248				
<i>15</i> .	6461.15488	4454.55561				
	6490.16468	4463.16751				
AREA = 7.148 AC.						



FOREST G. JONES, EXECUTIVE SECRETARY, CITY OF SALEN PLANNING COMMISSION

IN THE CLERK'S OFFICE OF THE CIRCUIT COURT OF SALEM, VIRGINIA, THIS 

TESTEE: GARY CHANCE CRAWFORD

PLAT SHOWING SECTION No. 4

## "THE NORTHWOODS OF RIDGEWOOD FARM"

PROPERTY OF

HERITAGE BUILDERS LTD. OF ROANOKE

BEING A RESUBDIVISION OF

TRACT "D3A" & TRACT "D4A", P.B. 5, PG. 60

TRACT F-2, P.B. 5, PG. 111

SITUATED ALONG OAK RIDGE LANE SALEM, VIRGINIA

SCALE: 1" = 50' DATE: 10 DECEMBER 1998

LUMSDEN ASSOCIATES, P.C. ENGINEERS - SURVEYORS - PLANNERS

ROANOKE, VIRGINIA COMM. #137LJ#4

SURVE.